NOTICE.—The SANBORN MAP & PUBLISHING CO. (Limited) will Loan, to parties purchasing one copy of this map, a Duplicate, with the mutual understanding and agreement that it is to be used exclusively by their General or Local Agent, and with the further agreement that, if not so used, one of the two copies will be returned to said Company.

No exposure.

Mc INTOSH ST.

Tenements

Storage 1st Cold Tow 2nd Storage

Ice Freezing

Machinery Compressor

Boiler Room

Well

COLUMBUS ICE & REFRIGERATING CO.

FUEL COAL. LIGHTS KEROSENE IN LANTERNS. CONSTANT WATCHMAN. 3 STEAM PUMPS & CITY WATER WORKS. PIPES ON PREMISES. HOSE SUFFICIENT. PROTECT ALL PARTS OF BUILDING. 1 DOZEN IRON FIRE PAILS.

WASHINGTON ST.

ORPHAN ASYLUM

No exposure

Hyd.

Shed.

Coal Bin on Roof.

CENTRAL R. R. OF GEORGIA COTTON COMPRESS
(Built 1884.)

CONSTANT WATCHMAN. FUEL COAL. LIGHTS GAS. 750' 4½" HOSE. 7 HYDRANTS. HOSE 50' TO 100' HOSE ATTACHED AT ALL TIMES. 100 IRON FIRE BUCKETS.

Platform 3' high.

Compress Tin Cl.

Platform 3' high.

No exposure Vacant 1½ Mile

No exposure.

Shed

Hunk Drive.

SWITCH TRACKS

No exposure.

SWIFT MF'G. CO. COTTON MILLS
MF'G. OF CHECKS - STRIPES AND MITCHELLINE CLOTH.

HEAT & POWER STEAM. FUEL COAL. LIGHTS KEROSENE-ELECTRIC & STEELING. USE. OWNER PREMISES SUBJECT TO BE LIGHTED BY ELECTRIC LIGHT. CONSTANT WATCHMAN. WATCHCLOCK AT NIGHT. 4 STATIONS. 400' HOSE TO 1 TANK, IN TOWER - 1000 GALLONS EACH. 50' 2½" HOSE CONNECTED TO VERT. PIPE EACH START. 400' HOSE ON PREMISES. BALL & BUCKETS & SPRINKLER PIPES ON 1ST & 2ND & 3RD & BASE. STEAM JETS EACH FLOOR. IRON FIRE BUCKETS.

Hose House

Hyd.

Tanks

Well

Vent Pipe

Storage Bast.

Weaving

Sky Light

Sprool & Stusher Rm. 3rd

Mach. Shop Basem.

Belt

Dye Ho.

Dry Room 2nd

Bleach House

Tank.

Coal Bin

A. B. C. D. E. F.

13

Hyd.

G. Office

Fence

Coal Wood & Brick Yard

Switch Tracks

Central Railroad Track Bridge

Open Shed

H. I. J.

FRANKLIN

Hyd.

MERCER

Dry.

P. O. N. M. K. J. I. H. G. F. E.

Muscogee Oil Mills

POWER STEAM. FUEL HULLS. LIGHTS GAS. STEAM HEAT IN OFFICE. CONSTANT WATCHMAN. 300' 2½" HOSE FOR OUTSIDE HYDRANTS. 750' 4½" HOSE - 50' ATTACHED TO VERT. PIPE EACH START. AUTOMATIC SPRINKLERS IN LINTER ROOM. NO CLEANING MACHINE. RUN AT NIGHT.

Road to Cotton Compress

4½" Pipe

Seed Ho.

Seed Screen

B.

Gin House

G.

C.

Storage Linters 2nd

Oil Tanks 1st Grinding 1st Hydraulic Press 2nd Separator 3rd

Engs. Boil.

Think on Posts

Barrels Cleaning

Hyd.

A. D. E. F.

THIRD AVE.

No exposure

ST. CLAIR ST.

Vacant opposite.

No exposure

GOLDEN BROS.
FOUNDRY AND MACH. SHOP
NO LIGHTS NO FIRE APPARATUS.

Cupola

Blacksmith

Foundry

Mach. Shop

Hyd.

A. B. C. D.

Fr. Bldg. opposite.

No exposure

General Mechdise

Groc.

Well

Mere House

Railroad Freight House (not used)

Scale of Feet.

50 40 30 20 10 0 50 100 150

WILLINGHAM & CO.
PLANING MILL
SASH, DOOR AND BLIND FACTORY.

FUEL SHAVINGS. NO HEAT OR LIGHT. STEAM PUMP & 750' 2½" HOSE. HEAT & PIPES AT OFF FOREMAN. CHEMICAL EXT. UNDER SHED NORTHSIDE OF WARE NO.

Planing 1st Bench Work 2nd

Engs. Asy.

Think

Lumber Shed

BRYAN

Scale.